

KENTUCKY HISTORIC RESOURCES  
INDIVIDUAL SURVEY FORM  
(KHC 2002-1)

COUNTY Lewis \_\_\_\_\_  
RESOURCE # Lw-66  
RELATED GROUP # \_\_\_\_\_  
EVALUATION S  
SHPO EVALUATION S  
DESTROYED \_\_\_\_\_

For instruction, see the Kentucky Historic Resources Survey Manual.

1. NAME OF RESOURCE (how determined): 9/ House

19. FOUNDATION:

<u>TYPE</u>	<u>MATERIAL</u>
2 / Continuous	D/ Rusticated Block original
/	/ replacement

2. ADDRESS/LOCATION:

South side, State Route 8, just west of intersection of SR 8 and Industrial Park Drive  
Buena Vista, KY. 41179

3. UTM REFERENCE:

Quad. Name: Vanceburg

Date: 1991 / Zone: 17 / Accuracy: A  
Easting: / 3/ 0/ 2/ 3/ 2/ 8/

Northing: 4 / 2/ 7/ 4/ 2/ 2/ 6/

4. OWNER/ADDRESS:

5. FIELD RECORDER/AFFILIATION:

Kate Carothers/ Environment & Archaeology, LLC.

6. DATE RECORDED:

9-2-05

7. SPONSOR:

Cellco Partnership d/b/a Verizon Wireless

8. INITIATION: 3 / Review & Compliance  
Buena Vista / Applegate cell site

9. OTHER DOCUMENTATION/RECOGNITION:

<input type="checkbox"/> Survey	<input type="checkbox"/> HABS/HAER
<input type="checkbox"/> KY Land	<input type="checkbox"/> Local Land
<input type="checkbox"/> NR	<input type="checkbox"/> NHL

Other:  
Report Reference

10. ORIGINAL PRIMARY FUNCTION: 0/1 /A /  
Single family home

11. CURRENT PRIMARY FUNCTION: 0/1 / A /  
Single family home

12. CONSTRUCTION DATE: 3 / c. 1910's estimated  
/ / / / / documented

13. DATE OF MAJOR MODIFICATIONS:

/  
/

14. CONSTRUCTION METHOD/MATERIAL:

W 3 / Frame original  
/ / subsequent

15. DIMENSIONS:

Height stories 1.5 Width bays 3 Depth bays 2

16. PLAN:

U / Undetermined first  
/ second  
/ third

17. STYLISTIC INFLUENCE:

/ ; / first  
/ ; / second  
/ ; / third

18. STYLE DEVELOPMENT:

R / first / second / third

20. PRIMARY WALL MATERIAL:

<u>I/</u> Weatherboard	original
Y / Vinyl siding	replacement

21. ROOF CONFIGURATION/COVERING:

<u>CONFIGURATION</u>	<u>COVERING</u>
B / Gable, front	7 / Standing-seam metal original
/	/ replacement

22. CONDITION: G / Good

23. MODIFICATION: 3/ Major unsympathetic alteration

24. NEGATIVE FILE #: \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Write resource # on back of all prints.



COMMENTS/HISTORICAL INFORMATION:


Located on the south side of State Route 8, this property is a 1.5 story 3-bay cottage with a standing-seam metal roof, clad in vinyl siding. Windows are small 1/1 vinyl replacement windows, and appear to have been reduced in size. An almost-full-width hipped-roof front porch spans the façade, and is supported by wooden posts. The porch foundation is concrete block, and appears to have been added later.

A large timber-framed barn, presumably for horses, 2 small sheds, and a small concrete block building comprise the outbuildings on the property. The barn was indicated on the 1949 topographic map of the area.

## 25. SUPPORT RESOURCES: SITE PLAN KEY

	FUNCTION	CONSTRUCTION DATE	METHOD MATERIAL
A	Barn/ Horses/ Storage/	c. 1920	W/3/Frame
B	Sheds/ Storage (2)	c. 1950-1960	W/3/ Frame
C	Shed/Storage	c. 1970	P/I/ Concrete block

## 26. SITE PLAN (Complete if #25 was answered).



## 27. MAP (Scan or attach copy of map showing exact location of resource)

